#### TTC STATUS

- LEADE - 02/08/2004-Sophie BARON PH-ESS

#### TTC status


- Proposal for the support organisation
- Technical report
  - o TTC modules
  - o TTC global maintenance
  - o TTC future plans

### Organisation proposal - 1/2

- Hardware procurement and testing:
  - o PH-ESS: M. Joos and S. Baron
  - o PH-ATE: P. Gallno, P. Donnat
- TTC signal distribution from PCR to the experiments:
  - Timing signal provision to the PCR: AB-RF
  - o Fibers: TS-EL
  - o Encoders, transmitters, receivers & signal quality at the input of experiments: PH-ESS
- Support of TTC distribution within the experiments:
  - Experiments themselves

#### Organisation proposal - 2/2

- Technical discussions:
  - Lightweight group reporting to LEADE:



Experiments: ALICE: Fabio Formenti

ATLAS: Philippe Farthouat

CMS: Jan Troska

LHCb: Richard Jacobsson

AB: .......

.....

PH-ESS: Sophie Baron

Markus Joos

### Technical report - modules 1/2


#### TTC Modules:

- o TTCrq
  - Test System stability
    - Work with Paulo Moreira on stabilization of the system (add extra delays due to Qpll)
  - Yield improvement
    - ~11% failure in the last batch
    - 1/3 of the failure rate due to Qpll (soldering? Default?)
    - New batch of 2000pces in September

#### Technical report - modules 2/2

#### o TTCex

- Test setup installation
  - Use of Bruce's scope for jitter & phase measurement
  - Test procedure
- TTCrq/ex compatibility
  - Current stand-alone frequency: 40.0845MHz => out of the Qpll locking range
  - Replace the zener diode controlling the VCXO: 6.2V => 2.4V
    - » CLK = 40.0811MHz,
    - » Just inside the Qpll range ~ [40.0757;40.0816] (40.078686+-3kHz)
    - » Frequency track test is running




# Technical report - global system 1/3

- TTC global system
  - o 25ns run story (June 04)
    - Optical fibers were cut in BA81 => no signal at H8, H4 and H2
    - Many days to discover the origin of the problem
    - Conclusions
      - lack of diagnosis tools
      - coordination was really missing

# Technical report - global system 2/3

#### o BST/TTC


- 2 systems in parallel
- Same transmission protocol...
- Different needs in term of jitter
- BST upgrade in progress
  - 3 BST crates will be released soon
  - Collaboration with BST people would be very helpful



#### Technical report-global system 3/3

#### o PCR status

Crates connectivity - well understood



- At present: 2 complete crates to share with BST, including Hi-power laser
- Autumn: BST upgraded => no use of these crates anymore

# Technical report - future plans 1/3

- Re-installation of the fibers patch panel in B4 => available mid-September (before the next 25ns run)
  - o 4 single-mode, 4 multi-mode, from PCR to Build4
  - Support during the runs (mirror of signals received by experiments)
  - o jitter measurement for TTC and BST
  - Evaluation of new developments
- Map of the overall optical connections
  - o To be updated this week by TS/EL (Oystein Olsen)
- TTC mailing list
- New oscilloscopes for jitter measurement (Lecroy Wavepro 7100)
  - 1 GHz, 20/10 GS/s, 1Mpts/ch, 2ps jitter noise floor, jitter option
  - Purchase in progress,
  - o 1 at ESS, 2/3 at Pool => contact Catherine Moine

### Technical report - future plans 2/3

- Next 25ns run (5-8 October 04)
  - o run with the current modules with the current spares
  - Coordination:
    - Correct diagnosis must be made by experiments
      - Check list to help them will be prepared
    - Spares will be available to be shared with BST if not upgraded
    - Short term: S. Baron on call (160494) during the run for the TTC from PCR to experiment areas
    - Longer term: to be defined in the light of future hardware developments (local/remote diagnosis tools and procedures)

#### Technical report - future plans 3/3

- TTC system upgrade => discussion needed
  - o Needs:
    - Remote diagnosis
    - Maintenance & support. No piquet available => need some intelligence in the system
    - Production of enough spares technical support
  - 3 modules could be developed...following Bruce's philosophy...but with some remote control
    - Encoder
    - Transmitter
    - Receiver with TTCrq & diagnosis for maintenance
  - Collaboration with the BST people (AB/CO- AB/BDI)
    - BST system : an example of maintained system
    - Homogeneous equipment as much as possible
    - Common maintenance procedures/tools for persons on shift